



Manhole Inspection Form

M1-3-3-2



Manhole Number	M1-3-3-2	Historic Manhole Number	Rosebriar 2
Year Installed	1992	Structure Type	Sanitary Manhole
Street	Rosebriar	Address	26323
Elevation	591.838	Weather	Sunny
Temperature	65°	Ground Condition	Dry
Status	At Surface Grade	Location	Field
Pavment Condition	N/A	Traffic	No Traffic at Location
Inspector 1	Rbc	Inspector 2	Cad
Cover Type	EJ 1040APT	Number of Cover Holes	3 - 5
Catch Basin Cover	N/A	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is At Grade
Grade Dist	<null>	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	None	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	<null>
Manhole Diameter	48	Manhole Depth	12.05
Chimney Depth	<null>	Chimney Construction	Block
Chimney Condition	Good	Chimney Inflow	None
Cone Shape	<null>	Cone Depth	<null>
Cone Construction	Precast	Cone Condition	Fair
Cone Inflow	Low	Cone Defect Location	Wall/Cone Joint
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	None	Wall Defect Location	<null>
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Fair
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Fair	Channel Inflow	None
Channel Hydraulics	Fair	Channel Exposure	Fully



Manhole Inspection Form

M1-3-3-2



Step Construction	Plastic	Step Condition	Fair
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	10
Pipe 1 Direction	S	Pipe 1 Depth	11.85
Pipe 1 Material	Truss	Pipe 1 Seal Condition	Poor
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	10
Pipe 2 Direction	NE	Pipe 2 Depth	12.05
Pipe 2 Material	Truss	Pipe 2 Seal Condition	Poor
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Vactor Clean	Recommendation 2	Seal Wall Joints
Recommendation 3	Point Pipes	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



Manhole Inspection Form

M1-3-3-2



Recommendation 7

<null>

Recommendation 8

<null>

Manhole Rating

3 – Failure likely in 10 to 20 years
(Fair) Comments



Manhole Inspection Form

M1-3-3-2





Manhole Inspection Form

M1-3-3-2



Civil Engineers • Surveyors • Architects 586-726-1234 Page: 8

Date: 6-28-17
Address: 26323 Rosebarn
R.T. = 12.05'
D = 48"
Map: 78


Manhole Number: M1-3-3-2
Community: Chesterfield
Inspector Initials: CAD / RBC

NORTH
S
E
W

EJ1040APT
2.50'
20"
48"

NE truss 12.05' 10" P
S truss 11.85' 10" P


Photograph This Document! www.aeswinc.com



Manhole Inspection Form

M1-3-3-2





Manhole Inspection Form

M1-3-3-2

