



Manhole Inspection Form

M1-5-3-3-17-3-5A



Manhole Number	M1-5-3-3-17-3-5A	Historic Manhole Number	Noble 6
Year Installed	1995	Structure Type	Sanitary Manhole
Street	Royal	Address	45867
Elevation	592.962	Weather	Sunny
Temperature	20°	Ground Condition	Frozen
Status	At Surface Grade	Location	Yard Back
Pavment Condition	N/A	Traffic	No Traffic at Location
Inspector 1	Kmd	Inspector 2	Brs
Cover Type	Ej1040apt	Number of Cover Holes	Solid Cover
Catch Basin Cover	<null>	Cover Insert	No
Cover Gasket	Yes	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Good Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	Low	Frame Riser	No
Frame Riser Height	<null>	Frame Riser Material	N/A
Manhole Diameter	48	Manhole Depth	11.15
Chimney Depth	0.4	Chimney Construction	Brick
Chimney Condition	Good	Chimney Inflow	None
Cone Shape	Eccentric	Cone Depth	36
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	None	Cone Defect Location	None
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	Low	Wall Defect Location	Lift Holes
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Yes



Manhole Inspection Form

M1-5-3-3-17-3-5A



Step Construction	Plastic	Step Condition	Good
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	12
Pipe 1 Direction	W	Pipe 1 Depth	11.15
Pipe 1 Material	Truss	Pipe 1 Seal Condition	Good
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	12
Pipe 2 Direction	E	Pipe 2 Depth	11.15
Pipe 2 Material	Truss	Pipe 2 Seal Condition	Good
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Internal Chimney Seal	Recommendation 2	Seal Lift Holes
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



Manhole Inspection Form

M1-5-3-3-17-3-5A



Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	



Manhole Inspection Form


M1-5-3-3-17-3-5A





Manhole Inspection Form

M1-5-3-3-17-3-5A






Manhole Inspection Form

M1-5-3-3-17-3-5A





Manhole Inspection Form

M1-5-3-3-17-3-5A

