



Manhole Inspection Form

M2-16-36-P5-2WA



Manhole Number	M2-16-36-P5-2WA	Historic Manhole Number	Sugarbush 1C
Year Installed	1971	Structure Type	Sanitary Manhole
Street	Sugarbush	Address	48469
Elevation	587.495	Weather	Overcast
Temperature	80°	Ground Condition	Dry
Status	At Surface Grade	Location	Paved Asphalt
Pavment Condition	Fair	Traffic	Two to Three Lane Road
Inspector 1	Jef	Inspector 2	Amc
Cover Type	EJ 1040APT	Number of Cover Holes	Solid Cover
Catch Basin Cover	N/A	Cover Insert	No
Cover Gasket	No	Cover Grade	Cover is At Grade
Grade Dist	0	Cover Fit	Tight Fit
Cover Condition	Good	Frame Condition	Good
Frame Offset	<null>	Frame Seal Condition	Good
Frame Seal Inflow	None	Frame Riser	<null>
Frame Riser Height	<null>	Frame Riser Material	<null>
Manhole Diameter	48	Manhole Depth	12.55
Chimney Depth	0.6	Chimney Construction	Brick
Chimney Condition	Good	Chimney Inflow	None
Cone Shape	<null>	Cone Depth	24
Cone Construction	Precast	Cone Condition	Good
Cone Inflow	Low	Cone Defect Location	Wall/Cone Joint
Wall Construction	Precast	Wall Condition	Good
Wall Inflow	None	Wall Defect Location	Wall Joint
Wall Defect Location 2	<null>	Wall Defect Location 3	<null>
Wall Defect Location 4	<null>	Wall Defect Location 5	<null>
Bench Construction	Poured	Bench Condition	Good
Bench Inflow	None	Channel Construction	Poured
Channel Condition	Good	Channel Inflow	None
Channel Hydraulics	Good	Channel Exposure	Fully



Manhole Inspection Form

M2-16-36-P5-2WA



Step Construction	Iron	Step Condition	Poor
Surcharge Evidence	<null>		
Pipe 1 Flow	Inward Flow	Pipe 1 Diameter	12
Pipe 1 Direction	W	Pipe 1 Depth	12.5
Pipe 1 Material	Concrete	Pipe 1 Seal Condition	Fair
Pipe 1 Drop	<null>	Pipe 1 Comments	<null>
Pipe 2 Flow	Outward Flow	Pipe 2 Diameter	12
Pipe 2 Direction	E	Pipe 2 Depth	12.55
Pipe 2 Material	Concrete	Pipe 2 Seal Condition	Fair
Pipe 2 Drop	<null>	Pipe 2 Comments	<null>
Pipe 3 Flow	<null>	Pipe 3 Diameter	<null>
Pipe 3 Direction	<null>	Pipe 3 Depth	<null>
Pipe 3 Material	<null>	Pipe 3 Seal Condition	<null>
Pipe 3 Drop	<null>	Pipe 3 Comments	<null>
Pipe 4 Flow	<null>	Pipe 4 Diameter	<null>
Pipe 4 Direction	<null>	Pipe 4 Depth	<null>
Pipe 4 Material	<null>	Pipe 4 Seal Condition	<null>
Pipe 4 Drop	<null>	Pipe 4 Comments	<null>
Pipe 5 Flow	<null>	Pipe 5 Diameter	<null>
Pipe 5 Direction	<null>	Pipe 5 Depth	<null>
Pipe 5 Material	<null>	Pipe 5 Seal Condition	<null>
Pipe 5 Drop	<null>	Pipe 5 Comments	<null>
Pipe 6 Flow	<null>	Pipe 6 Diameter	<null>
Pipe 6 Direction	<null>	Pipe 6 Depth	<null>
Pipe 6 Material	<null>	Pipe 6 Seal Condition	<null>
Pipe 6 Drop	<null>	Pipe 6 Comments	<null>
Recommendation 1	Seal Wall Joints	Recommendation 2	<null>
Recommendation 3	<null>	Recommendation 4	<null>
Recommendation 5	<null>	Recommendation 6	<null>



Manhole Inspection Form

M2-16-36-P5-2WA



Recommendation 7	<null>	Recommendation 8	<null>
Manhole Rating	2 – Failure unlikely in 20 years (Good)	Comments	<null>



Manhole Inspection Form

M2-16-36-P5-2WA






Manhole Inspection Form

M2-16-36-P5-2WA





Manhole Inspection Form

M2-16-36-P5-2WA

